



11.2 K.. → DRS

K37, $n_e = 1400$ об/мин					200 Нм			
n_a [об/мин]	M_{amax} [Нм]	F_{Ra} [Н]	φ (i/R) [']	i	DR63 DRS71S DRS71M	DRS80	DRS90M	DRS90L DRS100M
13	200	5640	7	106.38				
14	200	5640	7	97.81				
17	200	5640	7	83.69				
19	200	5520	7	72.54				
21	200	5360	7	67.80				
24	200	5020	7	58.60				
28	200	4660	7	49.79				
31	200	4420	7	44.46				
37	200	4100	7	37.97				
39	200	3970	7	35.57				
47	200	3650	7	29.96				
49	200	3580	8	28.83				
56	200	3330	8	24.99				
60	195	3260	8	23.36				
69	185	3110	8	20.19				
82	180	2900	8	17.15				
91	175	2780	9	15.31				
107	165	2650	9	13.08				
115	160	2600	12	12.14				
133	160	2410	12	10.49				
157	160	2200	12	8.91				
176	155	2110	13	7.96				
206	150	1980	13	6.80				
220	145	1950	13	6.37				
261	140	1810	13	5.36				
352	125	1660	13	3.98				